ASBESTOS ASSE. SURVEY

H-K Building w: 15 Project Number: 0980193E

Project: G. HEILEMAN BREWERY "E"

Date Inspected: 03/28/89 Inspector: MARK VOTH Building Number: 15

Building Name: OLD KEG WASHING

SEATTLE, WASHINGTON 98134
Building Type: KEGGING

Year Constructed: 1940

******* AREA NUMBER: 01 AREA DESCRIPTION: 1st Floor					AREA AVERAGE % ASBESTOS: 27%				******	
LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	UNITS OF QUANTITY MEASURE	PIPE ID	EXP POT PL	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
along north wall-at ceiling	00-356344	30%	wrapped cardboard/paper pipe	OHA	64 ft. 4 in. O.D.	DW	23 111	\$571	\$357	\$92
along south wall-at ceiling	00-356344	30%	wrapped cardboard/paper pipe	OMA	80 ft. 4 in. O.D.		23 111	\$714		\$1,16
above keg line-along ceiling	00-356351		pipe covering	OMA	143 ft. 4 in. O.D.	HPS/R				\$2,07
northwest stairwell-along ceiling	00-356351	30%	pipe covering	OMA	17 ft. 6 in. 0.0.			\$221	\$138	\$35
near southeast corner-at keg line	00-356351	30%	pipe covering	OMA	44 ft. 4 in. O.D.			\$392		\$63
along north row of columns-at ceiling	00-356351	30%	pipe covering	AMO	63 ft. 4 in. O.D.			\$562		\$91
northwest corner-at ceiling	00-356351		pipe covering	OMA	8 ft. 6 in. O.D.	HPS/R	23 111	\$104	\$65	\$16
near west wall-along ceiling	00-356351		pipe covering	OMA	70 ft. 6 in. O.D.			\$909		\$1,47
along south wall-at ceiling	04-356345	40%	mjp on wrapped cardboard/paper	OMA	5 4 in. O.D.	DW	23 111	\$140		\$21
along north wall-at ceiling	04-356345		mip on wrapped cardboard/paper	AMO	7 4 in. O.D.	DW	23 111	\$197		\$30
•	04-356346	40%	1				23 111			
	04-356347	40%	{				23 111			
northwest corner-at ceiling	05-356348	7%	mjp on non-suspect pipe cover	AMO	2 4 in. O.D.	DW	23 111	\$56	\$31	\$8
near west wall-along ceiling	05-356348		mjp on non-suspect pipe cover	OMA	3 4 in. O.D.	DW	23 111	\$84	\$47	\$13
	05-356349	10%	1				23 111	1		
	05-356350	10%					23 111	ļ		
near southeast corner-at keg line	06-356352	3%	mjp on pipe covering	OMA	4 4 in. O.D.	HPS/R	23 111	\$112	\$62	\$17
northwest corner-at ceiling	06-356352	3%	mjp on pipe covering	OMA	2 6 in. O.D.	HPS/R	23 111	\$77	\$45	\$12
above keg line-along ceiling	06-356352		mjp on pipe covering	OHA	14 4 in. O.D.	HPS/R	23 111	\$393	\$219	\$61
above keg line-along ceiling	06-356352		mjp on pipe covering	OMA	2 6 in. 0.D.	HPS/R	23 111	\$77	\$45	\$12
along north row of columns-at ceiling	06-356352	3%	mjp on pipe covering	OMA	2 4 in. O.D.	HPS/R	23 111	\$56	\$31	\$8
near west wall-along ceiling	06-356352		mjp on pipe covering	OMA	1 6 in. O.D.	HPS/R	23 111	\$39	\$23	\$62
	06-356353	10%					23 111			

AREA COMMENTS

AREA # 01 TOTAL \$5,980 \$3,660 \$9,640

23 111

AREA AVERAGE % ASBESTOS: 25%

The materials are in good condition with minor contact and water damage. The materials are approximately 3' to 12' from the floor. At a minimum, it is recommended that the materials be repaired and monitored. If removal is planned, glove bag removal procedures are recommended. This appears to be a low traffic area.

AREA DESCRIPTION: 2nd Floor

06-356354

	SAMPLE			0&M	UNITS OF	PIPE		REMOVAL	REPLACEMENT	TOTAL
LOCATION OF THE MATERIAL	NUMBER	ASB	MATERIAL DESCRIPTION	CODE	QUANTITY MEASURE	10	POT P	COSTS	COSTS	COSTS
near S electrical panel-at heat exchange			pipe covering	OMA	17 ft. 4 in. O.D				\$95	\$247
north wall-near stairs near S electrical panel-heat exchanger	00-356340 01-356333		wrapped cardboard/paper pipe boiler/tank insulation	OMA OMB	12 ft. 4 in. 0.D 193 sq.ft.	. DW	38 11 38 11			\$174 \$9,820

HALL-KIMBRELL ENVIRONMENTAL INC.

AREA NUMBER: 02

Page 38

06/09/89

ASBESTOS ASSE SURVEY

H-K Building #: 15

Project Number: 0980193E

Project: G. HEILEMAN BREWERY "E"

Date Inspected: 03/28/89 Inspector: MARK VOTH Building Number: 15

Building Name: OLD KEG WASHING

SEATTLE, WASHINGTON 98134

Building Type: KEGGING Year Constructed: 1940

near S electrical panel-at heat exchange	01-356334 01-356335 02-356337	20% 20% 10%	mjp on pipe covering	OHA	2 4 in. 0.D.	HPS/R	38 111 38 111 38 111	\$56	\$31	\$87
noon o cross root panet at most exemange	02-356338 02-356339	10% 10%			2 4 1111 0101	111 0 7 K	38 111 38 111	430	451	~"
north wall-near stairs	03-356341 03-356342 03-356343	30% 40% 40%	mjp on wrapped cardboard/paper	OMA	3 4 in. O.D.	DW	38 111 38 111 38 111	\$84	\$47	\$131

AREA COMMENTS

AREA # 02 TOTAL \$5,851 \$4,608 \$10,459

The materials are in fair condition with minor contact and water damage. The materials are approximately 1' to 10' from the floor. At a minimum, it is recommended that the materials be repaired and monitored. If removal is planned, gross removal procedures are recommended. This appears to be a low traffic area.

BUILDING # 1	5 TOTAL	\$11,831	\$8,268	\$20,099